


SERVICE BULLETIN
3110/3140

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

Kühlschränke
Wendel komplett


Ersatzteilnummer	Länge (A) in mm	Modell
292 6212-00/8	350	RM 4210/11/12/13/15/30/31/32/33/35, RM 5210, RM 5211/15, RM/T 7600/01/05/50/51/55, RM/T 7800/01/05/50/51/55, RML 8550/51/55
292 6212-10/7	430	RM 4260/61/62/63/65, RM 4280/81/85, RM 4370/71
292 6212-20/6	259	RM 4200/01/03, RM 4400/01/05, RM 4360/61, RM 4365, RM 5400/01/05, RM 7360/61/65, RM 7400/01/05, RM 7550/51/55, RM 8400/01, RM 8405, RM 8500/01/05/50/51/55 RG/E 200, S105GE, T105GE, G/GE 105, GM 60B, GM65H, GM 90H, NK 105, RG/E 2000 RA 4420/21
292 6212-30/5	150	RM 4300/01 und RM 301 mit 50mbar
292 6212-60/2	198	RM 2191, RM 2202, RM 4180/81/85, RM 4210/11/12/13/15/30/31/32/33/35 und RM 5210/11/15 mit RM 2202 Aggregat, RM 4240, RM 4290/91/92, RM 5270/71/85 RM 7270/71/75/90/91/95, RM 7370/71/75/90/91 RM 7395, RMF 7390, RMH 7390 RM 7400/01/05 Bailey RMS 8400/01/05/60/61/65, RMS 8500/01/05, RMS 8550/51/55, RMD 8500/01/05/50/51/55 RM 4300/01 und RM 301 mit 30mbar
292 6212-70/1	171	RM 4223